TOP SECRET



PHOTOGRAPHIC INTERPRETATION REPORT

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

# IMPROVEMENTS TO AIR FACILITIES PAKISTAN

25X1

TOP SECRET

25X1

JUNE 1972
COPY NO 121
8 PAGES
PIR-020/72

ROUP 1: EXCLUDED FROM UTOMATIC DOWNGRADING



25X1

# TOP SECRET RUFF

IMPROVEMENTS TO AIR FACILITIES, PAKISTAN

### ABSTRACT

1. This report describes construction activity at 12 military airfields in Pakistan from late 1971 through early 1972, and includes a location map and selected photographs.

## INTRODUCTION

25X1
25X1

revealed a substantial number of improvements at 12 of the 14 known military airfields in Pakistan (Figure 1). The improvements observed in this six month time frame (both prewar and postwar) consist of runway extensions, construction of parallel taxiways, support facilities, hangarettes, and revetted hardstands. The photography of these missions was good with cloud-free cover.

### BASIC DESCRIPTION

Peshawar Airfield

25X1

3. Six hangarettes were under construction (one in a late stage). Four net-covered aircraft revetments and at least 11 vehicle revetments had been built. Eight storage revetments were under construction in the storage area.



FIGURE 1. LOCATION MAP


- 1 -

25X1

Sanitized Copy Approved for Release 2011/08/24 : CIA-RDP78T05162A000200010063-0

|   | TOP SECRET RUFF   | 20/(1  |
|---|---|--|
|   |   |  |
| nent air facilit<br>was in a late st<br>hangarettes were<br>Four aircraft re<br>late stages of o<br>pumphouse, and t<br>tanks, one pumph<br>trol center was | rfield was being converted from a reserve airfield by. A turnaround loop taxiway at the southeast end age of construction, four hangarettes had been constructed in late stages, and two were in early stages of construction. One area contained nine buried POL town support buildings. The other area contained seconds, and three support buildings. A probable contained alate stage of construction and contained one and three support buildings (Figure 2). | of the runway upleted, two construction. eas were in canks, one even buried POL umand and con- |
| Mianwali Airfiel  | d   | 25X1   |
| early stage of o  | parallel taxi<br>construction. Eight revetted hardstands had been t<br>es, five in mid-to-late stages and 18 in early stage<br>erved. Construction continued on the five other pa   | ges of constru-<br>reviously re-   |
| ported stands, one in a were observed.  | hangarettes. Five drive-through revaluation a mid-to-late stage and four in early stages of confight vehicle revetments had also been built (Figure 1).   | struction,   |
| Sargodha Airfie   |   | 25X1   |
| 6. Seven 1  | mangarettes have been completed. Four hangarettes were in early stages of construction.   | were in late   |
| been built. In  | neter (400-foot) overrum at the northeast end of the addition, eight hangarettes in early stages and the stages of construction were observed.  | 25X1<br>ne runway had<br>wo alert hard-  |
| Twelve hangaret   | llel taxiway was in an early-to-mid stage of const<br>tes were under construction, one in a late stage a<br>uction continued on five previously reported  | ruction. nd ll in early 25X1   |
| additional  | hangarettes (Figure 4).   | 25X1<br>25X1   |
| Lahore Airfield<br>9. The ru<br>north end was b   | nway was being resurfaced with asphalt, and the overing replaced and lengthened.  |  |
| Shorkot Road Ai   |   | 25X1   |
| 10. Const   | ruction was observed on support facilities and 15 is airfield was being converted from a reserve air  | nangarettes<br>field to a  |
| air facility. foot) overrun a   | airfield was being converted from a liasion field A $1,284$ -meter ( $4,215$ -foot) runway extension, a $275$ t the north end of the runway, and ten revetted hax additional revetted hardstands and four hangaret  | -meter (899-<br>rdstands had   |
| Jacobabad Airfi   | eld   | 25X1   |
| 12. A tur   | naround loop taxiway at the southeast end of the mands, and two aircraft revetments had been built.   | A  |
| Hyderabad Airfi<br>13. Four   | eld New aircraft revetments had been built.   | 25X1   |
| Mauripur Airfie   | ald   | 25X1   |
| 14. A tax   | tiway connecting the BEAGLE/B-57 aircraft parking for was observed under construction. Two net-covered built and two aircraft revetments were under cons  | revetted hard-   |
|   |   |  |

Sanitized Copy Approved for Release 2011/08/24 : CIA-RDP78T05162A000200010063-0



| Sanitized Copy Approved for Release 2011/08/24 : CIA-RDP78T05162A000200010063-0  | 25X<br>25X |
|--|------------|
| TOT SECRET ROTT  |            |
|  |            |
|  |            |
|  |            |
| REFERENCES   |            |
|  |            |
|  | 25X        |
|  |            |
|  |            |
|  |            |
|  |            |
|  |            |
|  |            |
|  |            |
|  |            |
| MAPS OR CHARTS   |            |
| AMS, Series U-502, Sheet NI42-12, scale 1:250,000<br>AMS JOG (G), Series 1501, Sheets NH43-5, NI43-13, scale 1:250,000 |            |
| AMS JOG (A), Series 1501, Sheets NG42-10,13; NH42-8,<br>14; NH43-1,2; NI42-16; NI43-14, scale 1:250,000                |            |
| CIA Base Map 76233 1-70  |            |
|  |            |
|  |            |
| REQUIREMENT  |            |

25X1

Sanitized Copy Approved for Release 2011/08/24 : CIA-RDP78T05162A000200010063-0

TOP SECRET